



PARTS LAYOUT

FRONT VIEW




BACK VIEW




WIRING DIAGRAM

P.C.B. WIRING



BLK - BLACK
 R - RED
 Y - YELLOW
 GRAY - GRAY
 W - WHITE

CHANNEL SW WIRING



C1 PB 5-110-S
 C2 BR 5-55-S
 C3 R 5-55-S
 C4 O 5-75-S
 C5 Y 5-85-S
 C6 BR 5-60-S
 C7 Y 5-60-S
 C8 GRAY 5-45-S
 C9 R 5-50-S
 C10 LB 5-80-S
 C11 BLK 5-110-S
 C12 O 5-70-S
 C13 PI 5-55-S

BLK - BLACK
 BR - BROWN
 R - RED
 O - ORANGE
 Y - YELLOW
 GR - GREEN
 LB - LIGHT BLUE
 PB - PRUSSIAN BLUE
 GRAY - GRAY
 PI - PINK

C14 BR 5-45-S
 C15 R 5-55-S
 C16 O 5-65-S
 C17 Y 5-75-S

